



Engineering
Product Advisory

Subject: Simplex Operation
Product: V422VI
Number: 1400-0036-01-00
Date: 05/09/03

PRODUCT: 7255-01 V422VI Vicoax Translator

PROBLEM: The Vicoax translator does not work with Kollector RS422 simplex communication.

SOLUTION: Vicoax translator software was modified to handle the Kollector format of RS422 simplex operation.

NOTES: Software revision of Vicoax translator fixing this problem is 1.2.